

Photo Report

ERF 1486, VERMONT,
HERMANUS,
CALEDON RD

Consultant:

Michelle Naylor | Env. Consultant | M.Sc., Pr. Sci. Nat., EAPSA cell: 083 245 6556 | tel: 028 316 1769 | fax: 086 585 2461 | michelle@lornay.co.za | www.lornay.co.za PO Box 1990, Hermanus, 7200

Lornay Environmental Consulting Pty Ltd | Reg 2015/445417/07





View of the Main Lynx Road leading southwest into Vermont suburb. Site is located on the right (west)



View of the Main Lynx Road leading southwest into Vermont suburb. Site is located on the right (west)



Entrance to the site from Lynx Avenue



View of the site off the R43, corner of Lynx Road, looking towards the west. Building on site are derelict buildings on site (not older than 60 years)



View of the site from the Corner of Lynx Avenue and the R43



View of the site from the corner of Lynx Avenue and the R43



View of the site from the corner of Lynx Avenue and the R43



View of Lynx Avenue heading north towards the R43, the site is on the left



South end of the site with neighbouring adjacent residential development visible



Middle of the site showing the depression where sand has been excavated many years ago